Office of Fight-Gount Chaineer. I Town 29 th. 1880 I have the honor to transmit herewith a letter from mr gran Finch Lampish of this district, recommend ing that there be furnished for Currituck Beach Light house one Let of first order hydraulie float lamps, To replace the old moderator lamper. I approve m. Timck, recommendation and respectfully ask that the chance te made. I am Sin your oft Serve Ochabevek la Admiral Maj Engr. Le H. Eng: John Rodgers Uset. Chairman Lot Board

Baltimore Mb. 9. November 29-1980. Dear Sir There is required from the L.M. Depot Tomphinsville M.J. S. Currituck. Beach Light House, one set first over Hydraulie float lamps, to replace the ob moderator lamps; which are very Very Respectfully Jour Old. Last Jean Funck Tampist. Gent O.E. Babcock W. Lt. Light Flouse Engineer 3th district Baltimore M. J.

1342 Light-House Establishment,

Office of Light-House Engineer, Little District,

No Inclosures

Multimore, Bud., November 3, 1900.

Currituck Beach Light-station, N. C. Subject Inspection of.

The Lighthouse Board.

Sies:

I have the honor to make report of an examination of the following light-station:

CURRITUCK BEACH, N. C., October 28, 1900.

With exceptions to be noted the station was in excellent order.

Respers' dwelling needs painting outside. The same was not clean. The oilhouse has a few rusted spots, not needing attention at present. The wharf is badly out of repair, but when the working party was there last March, I had not sufficient funds to repair it, and work cannot be done under the allotment for the current year. It seems to have been the policy not to put any more repairs on this wharf, and nothing of consequence has been done to it for about 13 years. But upon careful consideration I think it necessary for the convenient service of the station, and I recommend that it be renewed at such time as funds can be provided therefor. I estimate the cost at \$6.000. The leas revolving machinery was working very well, indeed, but the hubs of the chariot wheels are badly worn, and a new set of wheels should be provided and held in readiness. On account of the alarming reports sent in by the keeper about the danger from lightning from the electrical call bell system in the ad all the small wire con-

Inspection of. abject

the Lighthouse Board.

I have the honor to make report of an examination of the following Sirs: light-station:

CURRITUCK BEACH, N. C., October 28, 1900.

With exceptions to be noted the station was in excellent order.

Keepers' dwelling needs painting outside. The same was not clean. The oilhouse has a few rusted spots, not needing attention at present. The wharf is badly out of repair, but when the working party was there last March, I had not sufficient funds to repair it, and work cannot be done under the allotment for the current year. It seems to have been the policy not to put any more repairs on this wharf, and nothing of consequence has been done to it for about 13 years. But upon careful coasideration I think it necessary for the convenient service of the station, and I recommend that it be renewed at such time as funds can be provided therefor. I estimate the cost at \$8.000. The lens revolving machinery was working very well, indeed, but the hubs of the chariot wheels are badly worn, and a new set of wheels should be provided and held in readiness. On account of the alarming reports sent in by the keeper about the danger from lightning from the electrical call bell system in the tower, one electrical discharge having destroyed all the small wire connections, the fuses, and burned off the insulation from all wire in the tower, I decided to abandon the electric and introduce the pneumatic call system, and the tubing was sent down for that purpose. But upon personal examination, I find that the Coast Telephone service wire has been grounded through same wire as the bell service. This sends all the induced currents generated during electric storms through the small wires of the bell circuit. The high resistance induced by a large current naturally burned out the fuses, the small wires and the insulation. The electric bells will be restored at an early date.

Respectfully yours,

Lieutenant-Colonel, Corps of Engineers, U. S. A.,

Gighthouse Engineer.